

General Engine info	
Model and type of engine	CFM56-5B4/3
Current power rating of engine	5B3/3
EGT Margin of engine deg C	92.68
EGT Margin value date	7-Nov-16
Current Location	In storage / LHT BRU
Engine at date:	31-Dec-2016
Current TSN of engine:	18,467.05
Current CSN of engine:	11,192
Last installation /Shop input:	19-Dec-16
TSN of last installation / shop input:	18,467.05
CSN of last installation / shop input:	11,192

Non Limited Parts Information		
Name	Part Number	Serial Number
Shipping stand Cradle	AM-2718-C1	366
Shipping stand base	AM-2563-200	1088

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
<b>Engine Status</b>	In Storage

Engine Comments:	
QEC Kit P/N 642K9001-211, S/N 9098002	
EGT Margin reflects 5B5/3 thrust (CFM ECM)	
LPT Rear Frame inspection threshold - Ref Chp 05-21-03, SB 72-620	
Environmental Ops: China - NO, India - YES, ME - NO	

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
5B3/3	Multiple	8,808
5B4/3	Multiple	8,808
5B5/3	Multiple	8,808

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	EASA AD 2016-0239	29,316.56	10,849.51
Cycle Limit	2016-09-06 EASA AD 2015-0038	11,436	244
Date Limit	Engine Preservation	02 Nov 17	306

Last Shop Visit Information	
Time since last HSV	1,017.00 Hours 556 Cycles
Time since last SV	0.00 Hours 0 Cycles
Last Repair Agency	LHT BRU
Last SV Workscope	Lease Return Inspection
Airworthiness Release	28-Dec-16 EASA, FAA,

**LLP Parts**

Module Name	Name	Part Number	Serial No	Total Hours	Total Cycles	Cycles Used	Cycles Used	Cycles Used	Cycles Limit	Cycles Limit	Cycles Limit	Cycles Remaining	Cycles Remaining	Cycles Remaining
Fan Rotor	Fan Disk	338-001-504-0	MA216455	18,467.05	11,192	5B3/3	5B4/3	5B5/3	5B3/3	5B4/3	5B5/3	5B3/3	5B4/3	5B5/3
Fan Rotor	Fan Booster Spool	338-001-906-0	DE171432	18,467.05	11,192	3,730	6,906	556	30,000	30,000	30,000	18,808	18,808	18,808
Fan Rotor	Fan Shaft	338-010-601-0	DE171411	18,467.05	11,192	3,730	6,906	556	30,000	30,000	30,000	18,808	18,808	18,808
HPC Rotor	HPC Stg 1-2 Spool	1558M31G07	GWN0GGGN	18,467.05	11,192	3,730	6,906	556	20,000	20,000	20,000	8,808	8,808	8,808
HPC Rotor	HPC Stg 3 Disk	2116M23P01	XAEK4496	18,467.05	11,192	3,730	6,906	556	20,000	20,000	20,000	8,808	8,808	8,808
HPC Rotor	HPC Stg 4-9 Spool	2048M20G03	GWN0GACN	18,467.05	11,192	3,730	6,906	556	20,000	20,000	20,000	8,808	8,808	8,808
HPC Rotor	HPC Fwd Shaft	1386M56P03	GWN0GHRF	18,467.05	11,192	3,730	6,906	556	20,000	20,000	20,000	8,808	8,808	8,808
HPC Rotor	HPC CDP Seal	2116M25P01	GFF5E3GM	18,467.05	11,192	3,730	6,906	556	20,000	20,000	20,000	8,808	8,808	8,808
HPT Rotor	HPT Disk	1498M43P07	GWN0GDGR	18,467.05	11,192	3,730	6,906	556	20,000	20,000	20,000	8,808	8,808	8,808
HPT Rotor	HPT Front Airseal	2116M20P02	GWN0GC4E	18,467.05	11,192	3,730	6,906	556	20,000	20,000	20,000	8,808	8,808	8,808
HPT Rotor	HPT Front Shaft	2048M21P03	XAEK5497	18,467.05	11,192	3,730	6,906	556	20,000	20,000	20,000	8,808	8,808	8,808
HPT Rotor	HPT Rear Shaft	1864M90P07	TMT4S018	18,467.05	11,192	3,730	6,906	556	20,000	20,000	20,000	8,808	8,808	8,808
LPT Rotor	LPT Stg 1 Disk	336-001-804-0	PA031529	18,467.05	11,192	3,730	6,906	556	25,000	25,000	25,000	13,808	13,808	13,808
LPT Rotor	LPT Stg 2 Disk	336-001-909-0	PA032826	18,467.05	11,192	3,730	6,906	556	25,000	25,000	25,000	13,808	13,808	13,808
LPT Rotor	LPT Stg 3 Disk	336-002-006-0	DD764129	18,467.05	11,192	3,730	6,906	556	25,000	25,000	25,000	13,808	13,808	13,808
LPT Rotor	LPT Stg 4 Disk	336-002-105-0	PA031888	18,467.05	11,192	3,730	6,906	556	25,000	25,000	25,000	13,808	13,808	13,808
LPT Rotor	LPT Conical Support	338-077-502-0	BC938238	18,467.05	11,192	3,730	6,906	556	25,000	25,000	25,000	13,808	13,808	13,808
LPT Rotor	LPT Shaft	338-010-005-0	DC850052	18,467.05	11,192	3,730	6,906	556	25,000	25,000	25,000	13,808	13,808	13,808
LPT Rotor	LPT Case	338-117-407-0	DD260911	18,467.05	11,192	3,730	6,906	556	N/L	N/L	N/L	N/L	N/L	N/L
LPT Rotor	Turbine Rear Frame	338-171-705-0	PA061911	18,467.05	11,192	3,730	6,906	556	25,000	25,000	25,000	13,808	13,808	13,808

Authorising Signature \_\_\_\_\_

Date \_\_\_\_\_

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.

General Engine info	
Model and type of engine	CFM56-5B4/3
Current power rating of engine	5B3/3
EGT Margin of engine deg C	92.68
EGT Margin value date	7-Nov-16
Current Location	In storage / LHT BRU
Engine at date:	31-Dec-2016
Current TSN of engine:	18,467.05
Current CSN of engine:	11,192
Last installation /Shop input:	19-Dec-16
TSN of last installation / shop input:	18,467.05
CSN of last installation / shop input:	11,192

Non Limited Parts Information		
Name	Part Number	Serial Number
Shipping stand Cradle	AM-2718-C1	366
Shipping stand base	AM-2563-200	1088

**Module status**

Name	IIN#	Part Number	Serial No	TSN or TSO	CSN or CSO
Fan Rotor	1	338-070-707-0	AJ7047	18467.05	11192
HPC Rotor	2	1887M18G04	HPCEX4926	18467.05	11192
HPT Rotor	3	1887M11G04	HPTX4926	18467.05	11192
LPT Rotor	4	338-092-317-0	RU7808	18467.05	11192
Fwd Mount	5	642-2006-503	P4542	12461.23	8570
Aft Mount	6	642-2301-501	P3870	12461.23	8570

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
<b>Engine Status</b>	In Storage

Engine Comments:	
QEC Kit P/N 642K9001-211, S/N 9098002	
EGT Margin reflects 5B5/3 thrust (CFM ECM)	
LPT Rear Frame inspection threshold - Ref Chp 05-21-03, SB 72-620	
Environmental Ops: China - NO, India - YES, ME - NO	

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
5B3/3	Multiple	8,808
5B4/3	Multiple	8,808
5B5/3	Multiple	8,808

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	EASA AD 2016-0239	29,316.56	10,849.51
Cycle Limit	2016-09-06 EASA AD 2015-0038	11,436	244
Date Limit	Engine Preservation	02 Nov 17	306

Last Shop Visit Information	
Time since last HSV	1,017.00 Hours 556 Cycles
Time since last SV	0.00 Hours 0 Cycles
Last Repair Agency	LHT BRU
Last SV Workscope	Lease Return Inspection
Airworthiness Release	28-Dec-16 EASA, FAA,

\_\_\_\_\_  
Authorising Signature

\_\_\_\_\_  
Date

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.