

General Engine info	
Model and type of engine	CFM56-5B3/3
Current power rating of engine	5B4/3
EGT Margin of engine deg C	34.54
EGT Margin value date	19-May-21
Current Location	SRT Zurich
Engine at date:	30-Jun-2021
Current TSN of engine:	14,764.88
Current CSN of engine:	8,409
Last installation /Shop input:	19-Apr-21
TSN of last installation / shop input:	14,764.88
CSN of last installation / shop input:	8,409

Non Limited Parts Information			
Name	Part Number	Serial Number	
Shipping Stand Cradle	AM-2718-C1	393	
Shipping Stand Base	AM-2563-200	1227	

**LLP Parts**

Module Name	Name	Part Number	Serial No	Total Hours	Total Cycles	Cycles Used	Cycles Used	Cycles Limit	Cycles Limit	Cycles Remaining	Cycles Remaining
Fan Rotor	Fan Disk	338-001-504-0	MA233015	14,764.88	8,409	5B4/3	5B3/3	5B4/3	5B3/3	5B4/3	5B3/3
Fan Rotor	Fan Booster Spool	338-001-906-0	DD975773	14,764.88	8,409	7,984	425	30,000	30,000	21,591	21,591
Fan Rotor	Fan Shaft	338-010-601-0	DE172156	14,764.88	8,409	7,984	425	30,000	30,000	21,591	21,591
HPC Rotor	HPC Stg 1-2 Spool	1558M31G07	GWN0H9EP	14,764.88	8,409	7,984	425	20,000	20,000	11,591	11,591
HPC Rotor	HPC Stg 3 Disk	2116M23P01	XAEL5102	14,764.88	8,409	7,984	425	20,000	20,000	11,591	11,591
HPC Rotor	HPC Stg 4-9 Spool	2048M20G03	GWN0H9T3	14,764.88	8,409	7,984	425	20,000	20,000	11,591	11,591
HPC Rotor	HPC Fwd Shaft	1386M56P03	GWN0HARR	14,764.88	8,409	7,984	425	20,000	20,000	11,591	11,591
HPC Rotor	HPC CDP Seal	2116M25P01	GFF5E701	14,764.88	8,409	7,984	425	20,000	20,000	11,591	11,591
HPT Rotor	HPT Disk	1498M43P07	GWN0H7EK	14,764.88	8,409	7,984	425	20,000	20,000	11,591	11,591
HPT Rotor	HPT Front Airseal	2116M20P02	TMT5C263	14,764.88	8,409	7,984	425	20,000	20,000	11,591	11,591
HPT Rotor	HPT Front Shaft	2048M21P03	XAEL2117	14,764.88	8,409	7,984	425	20,000	20,000	11,591	11,591
HPT Rotor	HPT Rear Shaft	1864M90P07	TMT4S497	14,764.88	8,409	7,984	425	20,000	20,000	11,591	11,591
LPT Rotor	LPT Stg 1 Disk	336-001-804-0	DE172562	14,764.88	8,409	7,984	425	25,000	25,000	16,591	16,591
LPT Rotor	LPT Stg 2 Disk	336-001-909-0	DD764904	14,764.88	8,409	7,984	425	25,000	25,000	16,591	16,591
LPT Rotor	LPT Stg 3 Disk	336-002-006-0	DD764088	14,764.88	8,409	7,984	425	25,000	25,000	16,591	16,591
LPT Rotor	LPT Stg 4 Disk	336-002-105-0	DE172598	14,764.88	8,409	7,984	425	25,000	25,000	16,591	16,591
LPT Rotor	LPT Conical Support	338-077-502-0	DD765264	14,764.88	8,409	7,984	425	25,000	25,000	16,591	16,591
LPT Rotor	LPT Shaft	338-010-005-0	DE198921	14,764.88	8,409	7,984	425	25,000	25,000	16,591	16,591
LPT Rotor	LPT Case	338-117-407-0	DE124577	14,764.88	8,409	7,984	425	N/L	N/L	N/L	N/L
LPT Rotor	Turbine Rear Frame	338-171-705-0	PA123381	14,764.88	8,409	7,984	425	25,000	25,000	16,591	16,591

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
<b>Engine Status</b>	In Storage

Engine Comments:	
3QEC kit P/N NPN, S/N NSN, Less MVI items, Exhaust System, Inlet Cowl and parts as identified in the Accessory/QEC inventory.	
EGT Margin: 34.54 noted at -5B3/3 Thrust Rating (OEM Re-delivery Report dated 19 April 2021)	
Environmental Ops: China - No, India - No, ME - Yes	

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
5B4/3	Multiple	11,591
5B3/3	Multiple	11,591

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	N/A	N/A	N/A
Cycle Limit	EASA AD 2007-0221	25,000	16,591
Date Limit	N/A	N/A	N/A

Last Shop Visit Information	
Time since last HSV	1,174.80 Hours 425 Cycles
Time since last SV	0.00 Hours 0 Cycles
Last Repair Agency	SRT ZRH
Last SV Workscope	Lease Return check and Borescope
Airworthiness Release	19-May-21 EASA Dual Release

Authorising Signature \_\_\_\_\_

Date \_\_\_\_\_

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.

General Engine info	
Model and type of engine	CFM56-5B3/3
Current power rating of engine	5B4/3
EGT Margin of engine deg C	34.54
EGT Margin value date	19-May-21
Current Location	SRT Zurich
Engine at date:	30-Jun-2021
Current TSN of engine:	14,764.88
Current CSN of engine:	8,409
Last installation /Shop input:	19-Apr-21
TSN of last installation / shop input:	14,764.88
CSN of last installation / shop input:	8,409

Non Limited Parts Information			
Name	Part Number	Serial Number	
Shipping Stand Cradle	AM-2718-C1	393	
Shipping Stand Base	AM-2563-200	1227	

**Module status**

Name	IIN#	Part Number	Serial No	TSN or TSO	CSN or CSO
Fan Rotor	1	338-070-707-0	AJ7204	14764.88	8409
HPC Rotor	2	1887M18G04	HPCEX6089	14764.88	8409
HPT Rotor	3	1887M11G04	HPTXX6089	14764.88	8409
LPT Rotor	4	338-092-318-0	RU9219	14764.88	8409
Fwd Mount	5	642-2006-503	P5016	14764.88	8409
Aft Mount	6	642-2301-501	P4376	14764.88	8409

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
<b>Engine Status</b>	In Storage

Engine Comments:
3QEC kit P/N NPN, S/N NSN, Less MVI items, Exhaust System, Inlet Cowl and parts as identified in the Accessory/QEC inventory.
EGT Margin: 34.54 noted at -5B3/3 Thrust Rating (OEM Re-delivery Report dated 19 April 2021)
Environmental Ops: China - No, India - No, ME - Yes

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
5B4/3	Multiple	11,591
5B3/3	Multiple	11,591

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	N/A	N/A	N/A
Cycle Limit	EASA AD 2007-0221	25,000	16,591
Date Limit	N/A	N/A	N/A

Last Shop Visit Information	
Time since last HSV	1,174.80 Hours 425 Cycles
Time since last SV	0.00 Hours 0 Cycles
Last Repair Agency	SRT ZRH
Last SV Workscope	Lease Return check and Borescope
Airworthiness Release	19-May-21 EASA Dual Release

\_\_\_\_\_  
Authorising Signature

\_\_\_\_\_  
Date

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.