

General Engine info	
Model and type of engine	CFM56-7B26
Current power rating of engine	7B26
EGT Margin of engine deg C	67
EGT Margin value date	28-Mar-14
Current Location	In storage
Engine at date:	16-Nov-2017
Current TSN of engine:	40,093.92
Current CSN of engine:	28,452
Last installation /Shop input:	12-Dec-15
TSN of last installation / shop input:	35,234.20
CSN of last installation / shop input:	25,153

Non Limited Parts Information		
Name	Part Number	Serial Number
Shipping Stand Cradle	AM2811-2100	503
Shipping Stand Base	AM2563-227	783

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
Engine Status	In Storage

Engine Comments:
 QEC Kit P/N 654A0001-7121, S/N Y7092

LPT Rear Frame inspection SB 72-579R8 C/W @ Delta Tech Ops ETC: 24,644

EGT Margin is noted at B26K Thrust based on Est. EGT Margin Statement from Aeromexico, 4/30/14.
 EGT Margin at B22K Thrust: 80 deg. C (MPA Run @ 75% N1)

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
7B22	LPT Rotor [LPT Rear Frame]	892
7B24	LPT Rotor [LPT Rear Frame]	892
7B26	LPT Rotor [LPT Rear Frame]	892
7B27	LPT Rotor [LPT Rear Frame]	892

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	N/A	N/A	N/A
Cycle Limit	2008-03-09 EASA AD 2007-0104	29,344	892
Date Limit	N/A	N/A	N/A

Last Shop Visit Information			
Time since last HSV	5,946.55 Hours	3808 Cycles	
Time since last SV	4,859.72 Hours	3299 Cycles	
Last Repair Agency	JES TX		
Last SV Workscope	EEC Software Upgrade		
Airworthiness Release	13-May-15	FAA, EASA	

LLP Parts

Module Name	Name	Part Number	Serial No	Total Hours	Total Cycles	Cycles Used	Cycles Used	Cycles Used	Cycles Used	Cycles Limit	Cycles Limit	Cycles Limit	Cycles Limit	Cycles Remaining	Cycles Remaining	Cycles Remaining	Cycles Remaining
						7B22	7B24	7B26	7B27	7B22	7B24	7B26	7B27	7B22	7B24	7B26	7B27
Fan Rotor	Fan Disk	340-000-420-0	DF946023	5,946.55	3,808	509	0	3,299	0	30,000	30,000	30,000	30,000	26,192	26,192	26,192	26,192
Fan Rotor	Fan Booster Spool	340-000-816-0	DH681985	5,946.55	3,808	509	0	3,299	0	23,600	23,600	23,600	23,600	19,792	19,792	19,792	19,792
Fan Rotor	Fan Shaft	335-006-414-0	DF803963	5,946.55	3,808	509	0	3,299	0	30,000	30,000	30,000	30,000	26,192	26,192	26,192	26,192
HPC Rotor	HPC Stg 1-2 Spool	1558M31G04	GNW0LE32	16,794.55	11,063	2,716	5,048	3,299	0	20,000	20,000	20,000	20,000	8,937	8,937	8,937	8,937
HPC Rotor	HPC Stg 3 Disk	1590M59P01	XAEL8584	16,794.55	11,063	2,716	5,048	3,299	0	20,000	20,000	20,000	20,000	8,937	8,937	8,937	8,937
HPC Rotor	HPC Stg 4-9 Spool	1588M89G03	GNW0LN80	16,794.55	11,063	2,716	5,048	3,299	0	20,000	20,000	20,000	20,000	8,937	8,937	8,937	8,937
HPC Rotor	HPC Fwd Shaft	1386M56P03	GNW0LM9G	16,794.55	11,063	2,716	5,048	3,299	0	20,000	20,000	20,000	20,000	8,937	8,937	8,937	8,937
HPC Rotor	HPC CDP Seal	1523M35P01	GFF5ELRN	16,794.55	11,063	2,716	5,048	3,299	0	20,000	20,000	18,600	18,600	8,688	8,688	8,080	8,080
HPT Rotor	HPT Disk	1498M43P06	GNW0LH3F	16,794.55	11,063	2,716	5,048	3,299	0	20,000	20,000	20,000	20,000	8,937	8,937	8,937	8,937
HPT Rotor	HPT Front Airseal	1795M36P02	TMT6Y259	16,794.55	11,063	2,716	5,048	3,299	0	20,000	20,000	17,600	17,600	8,487	8,487	7,468	7,468
HPT Rotor	HPT Front Shaft	1873M73P01	XAEM6342	16,794.55	11,063	2,716	5,048	3,299	0	20,000	20,000	17,600	17,600	8,487	8,487	7,468	7,468
HPT Rotor	HPT Rear Shaft	1864M90P04	TMT7F596	16,794.55	11,063	2,716	5,048	3,299	0	20,000	20,000	20,000	20,000	8,937	8,937	8,937	8,937
LPT Rotor	LPT Stg 1 Disk	336-001-804-0	PA903763	5,946.55	3,808	509	0	3,299	0	25,000	25,000	25,000	25,000	21,192	21,192	21,192	21,192
LPT Rotor	LPT Stg 2 Disk	336-001-909-0	PA871623	5,946.55	3,808	509	0	3,299	0	25,000	25,000	25,000	25,000	21,192	21,192	21,192	21,192
LPT Rotor	LPT Stg 3 Disk	336-002-006-0	PA699494	5,946.55	3,808	509	0	3,299	0	25,000	25,000	25,000	25,000	21,192	21,192	21,192	21,192
LPT Rotor	LPT Stg 4 Disk	336-002-105-0	PA896290	5,946.55	3,808	509	0	3,299	0	25,000	25,000	25,000	25,000	21,192	21,192	21,192	21,192
LPT Rotor	LPT Rotor Support	340-301-702-0	DH704989	5,946.55	3,808	509	0	3,299	0	25,000	25,000	25,000	25,000	21,192	21,192	21,192	21,192
LPT Rotor	LPT Shaft	340-074-723-0	PA847269	5,946.55	3,808	509	0	3,299	0	25,000	25,000	25,000	25,000	21,192	21,192	21,192	21,192
LPT Rotor	LPT Rear Frame	340-166-206-0	DC064133	40,093.92	28,452	2,716	22,437	3,299	0	29,344	29,344	29,344	29,344	892	892	892	892
LPT Rotor	LPT Case	338-117-455-0	DC155510	40,093.92	28,452	2,716	22,437	3,299	0	N/L	N/L	N/L	N/L	N/L	N/L	N/L	N/L

Authorising Signature _____

Date _____

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.

General Engine info	
Model and type of engine	CFM56-7B26
Current power rating of engine	7B26
EGT Margin of engine deg C	67
EGT Margin value date	28-Mar-14
Current Location	In storage
Engine at date:	16-Nov-2017
Current TSN of engine:	40,093.92
Current CSN of engine:	28,452
Last installation /Shop input:	12-Dec-15
TSN of last installation / shop input:	35,234.20
CSN of last installation / shop input:	25,153

Non Limited Parts Information		
Name	Part Number	Serial Number
Shipping Stand Cradle	AM2811-2100	503
Shipping Stand Base	AM2563-227	783

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
Engine Status	In Storage

Engine Comments:
QEC Kit P/N 654A0001-7121, S/N Y7092
LPT Rear Frame inspection SB 72-579R8 C/W @ Delta Tech Ops ETC: 24,644
EGT Margin is noted at B26K Thrust based on Est. EGT Margin Statement from Aeromexico, 4/30/14.
EGT Margin at B22K Thrust: 80 deg. C (MPA Run @ 75% N1)

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
7B22	LPT Rotor [LPT Rear Frame]	892
7B24	LPT Rotor [LPT Rear Frame]	892
7B26	LPT Rotor [LPT Rear Frame]	892
7B27	LPT Rotor [LPT Rear Frame]	892

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	N/A	N/A	N/A
Cycle Limit	2008-03-09 EASA AD 2007-0104	29,344	892
Date Limit	N/A	N/A	N/A

Last Shop Visit Information	
Time since last HSV	5,946.55 Hours 3808 Cycles
Time since last SV	4,859.72 Hours 3299 Cycles
Last Repair Agency	JES TX
Last SV Workscope	EEC Software Upgrade
Airworthiness Release	13-May-15 FAA, EASA

HPT Blades

Name	Part Number	Serial No	TSN or TSO	CSN or CSO
HPT Blades	2100M96P02	890317 VARIOUS	16794.55	11063

Authorising Signature

Date

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.

General Engine info	
Model and type of engine	CFM56-7B26
Current power rating of engine	7B26
EGT Margin of engine deg C	67
EGT Margin value date	28-Mar-14
Current Location	In storage
Engine at date:	16-Nov-2017
Current TSN of engine:	40,093.92
Current CSN of engine:	28,452
Last installation /Shop input:	12-Dec-15
TSN of last installation / shop input:	35,234.20
CSN of last installation / shop input:	25,153

Non Limited Parts Information		
Name	Part Number	Serial Number
Shipping Stand Cradle	AM2811-2100	503
Shipping Stand Base	AM2563-227	783

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
Engine Status	In Storage

Engine Comments:	
QEC Kit P/N 654A0001-7121, S/N Y7092	
LPT Rear Frame inspection SB 72-579R8 C/W @ Delta Tech Ops ETC: 24,644	
EGT Margin is noted at B26K Thrust based on Est. EGT Margin Statement from Aeromexico, 4/30/14.	
EGT Margin at B22K Thrust: 80 deg. C (MPA Run @ 75% N1)	

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
7B22	LPT Rotor [LPT Rear Frame]	892
7B24	LPT Rotor [LPT Rear Frame]	892
7B26	LPT Rotor [LPT Rear Frame]	892
7B27	LPT Rotor [LPT Rear Frame]	892

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	N/A	N/A	N/A
Cycle Limit	2008-03-09 EASA AD 2007-0104	29,344	892
Date Limit	N/A	N/A	N/A

Last Shop Visit Information			
Time since last HSV	5,946.55 Hours	3808 Cycles	
Time since last SV	4,859.72 Hours	3299 Cycles	
Last Repair Agency	JES TX		
Last SV Workscope	EEC Software Upgrade		
Airworthiness Release	13-May-15		FAA, EASA

Module status

Name	IIN#	Part Number	Serial No	TSN or TSO	CSN or CSO
Fan Rotor	21	340-035-311-0	21X90317	40093.92	28452
I & 2 Brq Support Assy	22	340-035-403-0	22X90317	40093.92	28452
Fan Frame	23	340-035-513-0	23X90317	40093.92	28452
HPC Rotor	31	9324M68G02	31X90317	40093.92	28452
HPC Front Stator Assy	32	9324M66G02	32X90317	40093.92	28452
HPC Rear Stator Assy	33	1887M17G01	33X90317	40093.92	28452
Combustion Assy	41	9325M13G02	41X90317	40093.92	28452
HPT Nozzle Assy	51	9324M69G04	51X90317	40093.92	28452
HPT Rotor	52	9324M61G02	52X90317	40093.92	28452
HPT/LPT Nozzle Shroud A	53	9324M62G04	53X90317	40093.92	28452
LPT Rotor	54	338-092-306-0	54X90317	40093.92	28452
LPT Shaft Assy	55	340-035-804-0	55X90317	40093.92	28452
LPT Rear Frame Assy	56	340-035-905-0	56X90317	40093.92	28452
#3 Bearing Inlet Gearbox A	61	9324M54G04	61X90317	40093.92	28452
Transfer Gearbox Assy	62	340-050-705-0	62X90317	40093.92	28452
Accessory Gearbox Assy	63	340-046-504-0	63X90317	40093.92	28452

Authorising Signature

Date

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.