

General Engine info	
Model and type of engine	CFM56-7B27E
Current power rating of engine	7B27E
EGT Margin of engine deg C	46
EGT Margin value date	4-Oct-16
Current Location	JES/ Storage
Engine at date:	6-Oct-2016
Current TSN of engine:	0.00
Current CSN of engine:	0
Last installation /Shop input:	18-Oct-16
TSN of last installation / shop input:	0.00
CSN of last installation / shop input:	0

Non Limited Parts Information		
Name	Part Number	Serial Number
Shipping Stand Cradle	AM-2811-4800	1172
Shipping Stand Base	AM-2563-200	1837

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
Engine Status	In Shop

Engine Comments:	
QEC kit p/n QECNG737-546 s/n NSN	
EGT Margin is noted at -7B27E Thrust (Test Cell)	

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
7B27E	Multiple	20,000

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	N/A	N/A	N/A
Cycle Limit	N/A	N/A	N/A
Date Limit	Engine Preservation	04 Oct 17	363
Last Shop Visit Information			
Time since last HSV	Hours Cycles		
Time since last SV	0.00 Hours 0 Cycles		
Last Repair Agency			
Last SV Workscope	N/A		
Airworthiness Release			

LLP Parts

Module Name	Name	Part Number	Serial No	Total Hours	Total Cycles	Cycles Used	Cycles Limit	Cycles Remaining
						7B27E	7B27E	7B27E
Fan Rotor	Fan Disk	340-000-420-0	PC416326	0	0	0	30,000	30,000
Fan Rotor	Fan Booster Spool	340-000-816-0	PC470118	0	0	0	22,900	22,900
Fan Rotor	Fan Shaft	335-006-414-0	DV122173	0	0	0	30,000	30,000
HPC Rotor	HPC Stg 1-2 Spool	1558M31G07	FG80D259	0	0	0	20,000	20,000
HPC Rotor	HPC Stg 3 Disk	2116M23P01	XAEHN505	0	0	0	20,000	20,000
HPC Rotor	HPC Stg 4-9 Spool	2048M20G04	AWN10T1M	0	0	0	20,000	20,000
HPC Rotor	HPC Fwd Shaft	1386M56P03	AWN10KRF	0	0	0	20,000	20,000
HPC Rotor	HPC CDP Seal	2116M25P01	GFF5JG34	0	0	0	20,000	20,000
HPT Rotor	HPT Disk	2410M49P02	AWN10T20	0	0	0	20,000	20,000
HPT Rotor	HPT Front Airseal	2410M50P02	XAEGW674	0	0	0	20,000	20,000
HPT Rotor	HPT Front Shaft	2048M21P03	XAEKN006	0	0	0	20,000	20,000
HPT Rotor	HPT Rear Shaft	1864M90P04	TMTD4818	0	0	0	20,000	20,000
LPT Rotor	LPT Stg 1 Disk	340-301-001-0	DV397715	0	0	0	25,000	25,000
LPT Rotor	LPT Stg 2 Disk	340-301-101-0	DV398167	0	0	0	25,000	25,000
LPT Rotor	LPT Stg 3 Disk	340-301-201-0	DV397975	0	0	0	25,000	25,000
LPT Rotor	LPT Stg 4 Disk	340-301-301-0	DV397653	0	0	0	25,000	25,000
LPT Rotor	LPT Rotor Support	340-301-702-0	DV110142	0	0	0	25,000	25,000
LPT Rotor	LPT Shaft	340-074-723-0	DV202206	0	0	0	25,000	25,000
LPT Rotor	LPT Rear Frame	340-166-211-0	DK486698	0	0	0	N/L	N/L
LPT Rotor	LPT Case	340-305-003-0	DN621244	0	0	0	N/L	N/L

Authorising Signature _____

Date _____

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.

General Engine info	
Model and type of engine	CFM56-7B27E
Current power rating of engine	7B27E
EGT Margin of engine deg C	46
EGT Margin value date	4-Oct-16
Current Location	JES/ Storage
Engine at date:	6-Oct-2016
Current TSN of engine:	0.00
Current CSN of engine:	0
Last installation /Shop input:	18-Oct-16
TSN of last installation / shop input:	0.00
CSN of last installation / shop input:	0

Non Limited Parts Information		
Name	Part Number	Serial Number
Shipping Stand Cradle	AM-2811-4800	1172
Shipping Stand Base	AM-2563-200	1837

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
Engine Status	In Shop

Engine Comments:
QEC kit p/n QECNG737-546 s/n NSN
EGT Margin is noted at -7B27E Thrust (Test Cell)

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
7B27E	Multiple	20,000

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	N/A	N/A	N/A
Cycle Limit	N/A	N/A	N/A
Date Limit	Engine Preservation	04 Oct 17	363
Last Shop Visit Information			
Time since last HSV	Hours	Cycles	
Time since last SV	0.00 Hours	0 Cycles	
Last Repair Agency			
Last SV Workscope	N/A		
Airworthiness Release			

Module status

Name	IIN#	Part Number	Serial No	TSN or TSO	CSN or CSO
Fan Rotor	21	340-035-314-0	AZ7131	0	0
1 & 2 Brq Support Assy	22	340-035-405-0	DZ7155	0	0
Fan Frame	23	340-035-520-0	BZ5818	0	0
HPC Rotor	31	9324M68G05	HPCEU6165	0	0
HPC Front Stator Assy	32	9324M66G05	FCSGU6190	0	0
HPC Rear Stator Assy	33	9324M67G02	RCSHU6005	0	0
Combustion Assy	41	9325M13G05	CDNJU6059	0	0
HPT Nozzle Assy	51	9324M69G06	HPNKH6045	0	0
HPT Rotor	52	9324M61G08	HPTXU6083	0	0
HPT/LPT Nozzle Shroud A	53	9324M62G07	HPSTU6131	0	0
LPT Rotor	54	338-092-319-0	MR1180	0	0
LPT Shaft Assy	55	340-035-805-0	SZ7139	0	0
LPT Rear Frame Assy	56	340-035-908-0	NZ7592	0	0
#3 Bearing Inlet Gearbox A	61	9324M54G06	UM3921	0	0
Transfer Gearbox Assy	62	340-050-705-0	VX7007	0	0
Accessory Gearbox Assy	63	340-046-509-0	WX5876	0	0

Authorising Signature

Date

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.